


W E E K L Y O P E R A T I O N S R E P O R T

I. DOCUMENT ID#: CPI-OPS-7601-200309-AM1
II. TITLE: TAYLOR COGEN GONZALES WEEKLY OPERATIONS REPORT
III. START DATE: 03/09/20
IV. END DATE: 03/15/20

V. KEY METRICS:
 Cogen Production: 116,841 kWh
 % of Gross Load Served: 41.2%
 Net Grid After All Generation: 166,978 kWh
 Net Exports: 6,985 kWh
 Cogen Run-hours: 64.75 run-hours



VI. UNPLANNED OUTAGES:

1. Cylinder detonation brought the genset down on Thursday at 2:25 A.M. During the post-shutdown inspection, a coolant leak was discovered, and that coolant had entered the cylinder banks.

VII. OPERATING NOTES:

1. Post overhaul inspection completed on Wednesday. Downtime: 10 hours, 27 minutes.
2. Genset programed to run at 1,850 kW with load following.

VIII. UPCOMING:

1. Repairs for coolant leak and cylinder heads are currently underway and the estimated return to operations is 3/25/2020.